

# Product Change Notification

**Issue Date:** September 05, 2024

**Product Name:** Motherboard series

**Status:** Running change

This notice is to inform you of changes to the :

1. IMBA-H420-ECO-R10
2. KINO-DH420-R10
3. KINO-AH420-R10
4. HPCIE-Q470-R10
5. IMBA-ADL-Q670-R10
6. IMB-ADL-Q670-R10
7. IMB-ADL-H610-R10
8. KINO-ADLPS-C-R10
9. KINO-ADLPS-i3-R10
10. KINO-ADLPS-i5-R10
11. KINO-ADLPS-i7-R10

## Reason for Change

1. Intel® Ethernet Controller I225 shortage issues.

## Description of Change

1. Change LAN IC from Intel® Ethernet Controller I225-LM / I225-V to Intel® Ethernet Controller I226-LM / I226-V.

## Affected Model

Affected Model	New Version
IMBA-H420-ECO-R10	IMBA-H420-ECO-R11
KINO-DH420-R10	KINO-DH420-R11
KINO-AH420-R10	KINO-AH420-R11
HPCIE-Q470-R10	HPCIE-Q470-R11
IMBA-ADL-Q670-R10	IMBA-ADL-Q670-R11
IMB-ADL-Q670-R10	IMB-ADL-Q670-R11
IMB-ADL-H610-R10	IMB-ADL-H610-R11

KINO-ADLPS-C-R10	KINO-ADLPS-C-R11
KINO-ADLPS-i3-R10	KINO-ADLPS-i3-R11
KINO-ADLPS-i5-R10	KINO-ADLPS-i5-R11
KINO-ADLPS-i7-R10	KINO-ADLPS-i7-R11

**Affected by This Change**

- |                                                    |                                     |                                                |                                            |
|----------------------------------------------------|-------------------------------------|------------------------------------------------|--------------------------------------------|
| <input checked="" type="checkbox"/> Specifications | <input type="checkbox"/> Dimensions | <input checked="" type="checkbox"/> Appearance | <input type="checkbox"/> Package           |
| <input type="checkbox"/> Certification             | <input type="checkbox"/> Label      | <input checked="" type="checkbox"/> BIOS       | <input checked="" type="checkbox"/> Driver |

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

*Best Regards,  
Maixin Li  
Product Manager  
IEI Integration Corp.*