

Product Chang Notice

☐ Approval / ☒ Inform Sheet

DATE: 2021/02/04

Model No.	MS-98K9/MS-98L2/MS-98L1/MS-98H7	PCN NO.	IPC20210204001
ERP No.	609-98K9-010/020/030/060/070 609-98L2-010/020/030 609-98L1-010/020/030/040 609-98H7-040		
Priority:	☐ URGENT ☒ NORMAL		

Change Type	Old	New
☐ PCB Change		
☐ H/W Component Change		
☒ BIOS change	Refer to follow table	Refer to follow table
☐ Driver change		
☐ Others:		

Description:

Update BIOS version.

Explanation:

Follow Intel recommend to update BIOS PMC FW to Version: 300.2.11.1024.

Intel Document number: #618912.

- BIOS change table list:

Model	ERP	Old BIOS	New BIOS
MS-98K9	609-98K9-010	E98K9IMS.200	E98K9IMS.210
	609-98K9-020	E98K9IMS.100	E98K9IMS.110
	609-98K9-030		
	609-98K9-060	E98K9IMS.610	E98K9IMS.620
	609-98K9-070	E98K9IMS.510	E98K9IMS.520
MS-98L2	609-98L2-010	E98L2IMS.200	E98L2IMS.210
	609-98L2-020	E98L2IMS.110	E98L2IMS.120
	609-98L2-030		
MS-98L1	609-98L1-010	E98L1IMS.100	E98L1IMS.110
	609-98L1-020	E98L1IMS.200	E98L1IMS.210
	609-98L1-030/040	E98L1IMS.300	E98L1IMS.310
MS-98H7	609-98H7-040	E98H7IMS.110	E98H7IMS.210

☐ **ECN Inform Sheet :**

Customer's Reply:

☐ Accept

☐ Do not accept

Production Instruction:

☐ Cut in Immediately

☒ Running Change

☐ RMA Cut in

Explanation, Comments and Suggestions:

Issued By	Sharonpan	Reviewed By	
------------------	-----------	--------------------	--

Counter signature

☒ N/A