



BCM

Product Change Notice

PCN Type: ☒ HW/SYS/Kit ☐ BIOS/LAN/FW ☐ Package/Label ☐ Driver/OS ☐ Acc. ☐ Others Page: 1 of 1

PCN Number: P211103		Revision: A		Date of Publication: 03/17/2021
PRODUCT NAME	PRODUCT PART#	OLD	REV. — NEW	REVISION TYPE
BC246C	71585-IA	1.1	1.2	Hardware
BC246C	71586-IA	3.1	3.2	
BC370Q	71582-IA	3.1	3.2	
MX370QD	71135-IA	1.1	1.2	

REASON OF CHANGE:

Improve the device compatibility for devices that plug into the USB Type C port.

DESCRIPTION OF CHANGE:

For BC246C and BC370Q, change to 2.2uF on location C844.

For MX370QD, change to 2.2uF on location C71.

IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there is no quality, reliability or thermal implications to our customer.

BCM is not recommending our customer to perform additional qualification of this changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

CUT IN DATE:

Date: December, 2021

OR

Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on March, 2021.

This PCN had been **APPROVED** by BCM Procurement Department on March, 2021.

APPROVED BY

VP OF SALES	<APPROVED>	03/17/2021
-------------	------------	------------

Signature

Date