



BCM

Product Change Notice

PCN Type: HW/SYS/Kit BIOS/LAN/FW Package/Label Driver/OS Acc. Others Page: 1 of 2

PCN Number: P240701		Revision: A		Date of Publication: 02/13/2024
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
MX610H	71862-IA	1.10	1.30	BIOS
		1.00	1.01	LAN Image

REASON OF CHANGE:
 Improve computability with Raptor Lake processors.

DESCRIPTION OF CHANGE:
 Update Device ID on Ethernet PHY to align with Intel Best Known Configuration.
 BIOS
 File name: 71862130.rom
 Version#: 1.30
 Programming method: Using AMI Firmware Update Utility v5.16.00.0101 (AfuEfix64.efi) under UEFI

IMPACT OF CHANGE AND RECOMMEND ACTION:
 This change has been thoroughly evaluated to ensure that there are no quality and regulation implications to our customer.
 BCM is not recommending customer to perform additional qualification of this change.*

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
LAN	YES
BIOS	YES
Driver	NO*
Hardware	NO

*If customer is loaded with BCM provided drivers under Windows, no Driver changes is required.

CUT IN DATE:

Date: February, 2024

OR

Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process	X		
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 02/13/2024.
 This PCN had been **APPROVED** by BCM Procurement Department on February, 2024.

APPROVED BY

VP OF SALES	<APPROVED>	02/13/2024
--------------------	------------	------------

Signature

Date