

Technical Notice

Issue Date: July 23, 2024

Product Name: IEI standard products

Implementation Date: July 23, 2024

Implementation Status: Running change

This notice is to inform you of changes to the IMBA-R680 / IMBA-ADL-Q670 / IMB-ADL-Q670 / IMBA-ADL-H610 / IMB-ADL-H610 / KINO-ADL-H610 / KINO-ADLPS / IMBA-Q470 / IMBA-Q471 / IMB-Q470 / IMBA-H420 / IMB-H420 / KINO-DH420 / PCIE-Q470 / HPCIE-Q470 series.

Reason for Change

Intel® Ethernet Controller I225 shortage issues.

Description of Change

Change LAN IC from Intel® Ethernet Controller I225-LM/I225-V to Intel® Ethernet Controller I226-LM/I226-V.

Affected Model

Affected Model
IMBA-R680-R10
IMBA-ADL-Q670-R10
IMB-ADL-Q670-R10
IMBA-ADL-H610-R10
IMB-ADL-H610-R10
KINO-ADL-H610-R10
IMBA-Q470-R10
IMBA-Q471-R10
IMB-Q470-R10
IMBA-H420-R10
IMB-H420-R10
KINO-DH420-R10
KINO-ADLPS-C-R10
KINO-ADLPS-i3-R10
KINO-ADLPS-i5-R10
KINO-ADLPS-i7-R10

PCIE-Q470-R10

HPCI-E-Q470-R10

Affected by This Change

Specifications

Dimensions

Appearance

Package

Certification

Label

BIOS

Driver

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

Best Regards,

Maoxin Li

Project Manager

IEI Integration Corp.