

PRODUCT END OF LIFE (EOL) NOTICE

1. EOL PRODUCTS

Product Name	Description
HR902	Intel Ivy Bridge Com Express Type 2 module

2. EOL REASONS

- ☒ Intel has formally announced the listed PCH EOL plan for BD82QM67.

Supplier	Marketing Name
Intel	Intel® BD82QM67 Platform Controller Hub

3. EOL MILESTONES

Milestone	Definition	Date
Last Order Date	This is the date for customers to place their last order. The product will no longer be available after this date.	2019/07/01
Last Shipment Date	This is the last delivery date of the product. 1. This date is negotiable with DFI's headquarter or its branch offices. 2. The delivery date will highly depend on its actual lead time.	2020/07/01
End of Service Date	This is the date DFI will: - Discontinue updating software - Discontinue adding features - Discontinue new OS support - Discontinue bug fixes RMA services will be available depending on DFI's RMA policy.	2022/07/01

4. Recommended Product Replacements:

Product Name	Description
N/A	N/A

Approved by:

Reviewed by:

Prepared by:

Customer's Signature:

DFI Inc.

No.100, Huanhe St., Sijhih City, Taipei County 22154, Taiwan (R.O.C.)
Tel: +886-2-2694-2986 FAX: +886-2-2694-5815

Products Affected/Order Codes:

Part Number	Model Name	Description
770-HR9021-000G	HR902-BL3615QE	HR902-BL3615QE:i7-3615QE+HM65 W/Thermal solution R.A F/G RoHS
770-HR9021-000K	HR902-BL3615QE	HR902-BL3615QE:i7-3615QE+HM65 W/O Thermal solution R.A F/G RoHS
770-HR9021-010G	HR902-BL3615QE	HR902-B3615QE:i7-3615QE+QM67 R.A F/G RoHS
770-HR9021-310G	HR902-B3517UE	HR902-B3517UE:i7-3517UE+QM67 W/Thermal solution R.A F/G RoHS
770-HR9021-410G	HR902-B3610ME	HR902-B3610ME:i5-3610ME+QM67 W/Thermal solution R.A F/G RoHS
770-HR9021-500G	HR902-BL3120ME	HR902-BL3120ME:i3-3120ME+HM65 W/Thermal solution R.A F/G RoHS MOTHER BOARD
770-HR9021-500K	HR902-BL3120ME	HR902-BL3120ME:i3-3120ME+HM65 W/O Thermal solution R.A F/G RoHS(M/B)
770-HR9021-510G	HR902-B3120ME	HR902-B3120ME:i3-3120ME+QM67 W/Thermal solution R.A F/G RoHS
770-HR9021-510K	HR902-B3120ME	HR902-B3120ME:i3-3120ME+QM67 W/O Thermal solution R.A F/G RoHS
770-HR9021-511G	HR902-B3120ME	HR902-B3120ME:i3-3120ME+QM67 W/Thermal solution R.A Naim F/G RoHS
770-HR9021-800G	HR902-BL2610UE	HR902-BL2610UE:i7-2610UE+HM65 W/Thermal solution R.A F/G RoHS
770-HR9021-800K	HR902-BL2610UE	HR902-BL2610UE:i7-2610UE+HM65 W/O Thermal solution R.A F/G RoHS
770-HR9021-810G	HR902-BL2610UE	HR902-B2610UE:i7-2610UE+QM67 W/Thermal solution R.A F/G RoHS MOTHER BOARD
770-HR9021-910G	HR902-B2515E	HR902-B2515E:i5-2515E+QM67 W/Thermal solution R.A F/G RoHS
770-HR9021-910K	HR902-B2515E	HR902-B2515E:i5-2515E+QM67 W/O Thermal solution R.A F/G RoHS
770-HR9021-A00G	HR902-BL2310E	HR902-BL2310E:i3-2310E+HM65 W/Thermal solution R.A F/G RoHS MOTHER BOARD
770-HR9021-A00K	HR902-BL2310E	HR902-BL2310E:i3-2310E+HM65 W/O Thermal solution

DFI Inc.

No.100, Huanhe St., Sijhih City, Taipei County 22154, Taiwan (R.O.C.)
Tel: +886-2-2694-2986 FAX: +886-2-2694-5815

		R.A F/G RoHS M/B
770-HR9021-A01G	HR902-BL2310E	HR902-BL2310E:i3-2310E+HM65 W/Thermal solution R.A 雄宇國際 F/G RoHS MOTHER BOARD
770-HR9021-C00G	HR902-BL810E	HR902-BL810E:B810E+HM65 W/Thermal solution R.A F/G RoHS MOTHER BOARD
770-HR9021-C00K	HR902-BL810E	HR902-BL810E:B810E+HM65 W/O Thermal solution R.A F/G RoHS M/B
770-HR9021-C01G	HR902-BL810E	HR902-BL810E:B810E+HM65 W/Thermal solution R.A 雄 宇國際 F/G RoHS MOTHER BOARD
770-HR9021-C10G	HR902-BL810E	HR902-B810E:B810E+QM67 W/Thermal solution R.A F/G RoHS MOTHER BOARD
770-HR9021-D00G	HR902-BL847E	HR902-BL847E:847E+HM65 W/Thermal solution R.A F/G RoHS MOTHER BOARD
770-HR9021-D00K	HR902-BL847E	HR902-BL847E:847E+HM65 W/O Thermal solution R.A F/G RoHS(M/B)
770-HR9021-E00G	HR902-BL847E	HR902-BL827E:827E+HM65 W/Thermal solution R.A F/G RoHS
770-HR9021-E00K	HR902-BL847E	HR902-BL827E:827E+HM65 W/O Thermal solution R.A F/G RoHS
770-HR9021-E01G	HR902-BL847E	HR902-BL827E:827E+HM65 W/Thermal solution R.A 雄宇 國際 F/G RoHS
770-HR9021-E10G	HR902-BL847E	暫不投產 HR902-BL827E:827E+QM67 W/Thermal solution R.A F/G RoHS MOTHER BOARD
770-HR902G-510G	HR902-B3120ME	HR902-B3120ME:i3-3120ME+QM67 W/Thermal solution R.A1 F/G RoHS
770-HR902G-991G	HR902-B2515E	HR902-B2515E:i5-2515E+QM67 W/Thermal solution R.A1 Sunwa/Sodick F/G RoHS
770-HR902G-A91G	HR902-B2310E	HR902-B2310E:i3-2310E+QM67 R.A1 Sunwa/Sodick F/G RoHS
770-HR902G-C10G	HR902-B810E	HR902-B810E:B810E+QM67 W/Thermal solution R.A1 F/G RoHS
777-HR9021-000G	HR902-BL3615QE	HR902-BL3615QE:i7-3615QE+HM65 W/O Thermal solution R.A F/G RoHS
777-HR9021-310G	HR902-B3517UE	HR902-B3517UE:i7-3517UE+QM67 W/O Thermal solution

DFI Inc.

No.100, Huanhe St., Sijhih City, Taipei County 22154, Taiwan (R.O.C.)
Tel: +886-2-2694-2986 FAX: +886-2-2694-5815

		R.A F/G RoHS
777-HR9021-500G	HR902-BL3120ME	HR902-BL3120ME:i3-3120ME+HM65 W/O Thermal solution R.A F/G RoHS(M/B)
777-HR9021-510G	HR902-BL3120ME	HR902-B3120ME:i3-3120ME+QM67 W/O Thermal solution R.A F/G RoHS
777-HR9021-910G	HR902-B2515E	HR902-B2515E:i5-2515E+QM67 W/O Thermal solution R.A F/G RoHS
777-HR9021-C00G	HR902-BL810E	HR902-BL810E:B810E+HM65 W/O Thermal solution R.A F/G RoHS M/B
777-HR9021-C10G	HR902-BL810E	HR902-B810E:B810E+QM67 W/O Thermal solution R.A F/G RoHS
777-HR9021-D00G	HR902-BL847E	HR902-BL847E:847E+HM65 W/O Thermal solution R.A F/G RoHS(M/B)
777-HR9021-E00G	HR902-BL827E	HR902-BL827E:827E+HM65 W/O Thermal solution R.A F/G RoHS
777-HR902G-991G	HR902-B2515E	HR902-B2515E:i5-2515E+QM67 W/O Thermal solution R.A1 Sunwa/Sodick F/G RoHS
777-HR902G-A91G	HR902-B2310E	HR902-B2310E:i3-2310E+QM67 W/O Thermal solution R.A1 Sunwa/Sodick F/G RoHS
774-HR9021-0A0G	HR902-B(17W+GT1)	HR902-B(17W+GT1): R.A Assy. RoHS 基礎 BOM 請勿下 單
774-HR9021-0B0G	HR902-B(25W/17W+GT2)	HR902-B(25W/17W+GT2): R.A Assy. RoHS 基礎 BOM 請勿 下單
774-HR9021-0C0G	HR902-B(45W/35W+GT2)	HR902-B(45W/35W+GT2): R.A Assy. RoHS 基礎 BOM 請勿 下單
774-HR9021-0D0G	HR902-BL(17W+GT1)	HR902-BL(17W+GT1): R.A Assy. RoHS 基礎 BOM 請勿下 單
774-HR9021-0E0G	HR902-BL(25W/17W+GT2)	HR902-BL(25W/17W+GT2): R.A Assy. RoHS 基礎 BOM 請 勿下單
774-HR9021-0F0G	HR902-BL(45W/35W+GT2)	HR902-BL(45W/35W+GT2): R.A Assy. RoHS 基礎 BOM 請 勿下單

DFI Inc.

No.100, Huanhe St., Sijhih City, Taipei County 22154, Taiwan (R.O.C.)
Tel: +886-2-2694-2986 FAX: +886-2-2694-5815