



BCM

Product Change Notice

PCN Type: HW/SYS/Kit BIOS/LAN/FW Package/Label Driver/OS Acc. Others Page: 1 of 1

PCN Number: P201502		Revision: A		Date of Publication: 04/15/2020
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
BC87Q	70943-C	1.1 (70942-C)	1.2 (70943-C)	Hardware
RX87Q	70905-C	3.1 (70903-C)	3.2 (70905-C)	

REASON OF CHANGE:

The Trusted Platform Module (TPM) 1.2 used on the RX87Q and BC87Q (Infineon SLB9635TT1.2) has been discontinued with no compatible replacement.

DESCRIPTION OF CHANGE:

TPM 1.2 will be phased out and removed from the bill of materials (BOM) of these two products. This phase out will coincide with the previously announced discontinuance date for these products of 2/26/2021 (see BCM **Change Notification #: E201401**)

IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there is no quality, reliability or thermal implications to our customer.

BCM is not recommending our customer to perform additional qualification of this changes.

AFFECTED BY THIS CHANGE	
Specification	YES
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

CUT IN DATE:

Date: 03/01/2021
OR
Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on March, 2020.
This PCN had been **APPROVED** by BCM Procurement Department on April, 2020.

APPROVED BY

CUSTOMER	<APPROVED>	04/15/2020
-----------------	------------	------------

Signature

Date

Doc#: F-G0-0-007A