


# Product Change Notification (PCN)

Title	USB Cable Appearance Changed	Date	2024/Jun/21	Ref No.	E240011
Models	EV2U-RMR1 and EV2U-RMR2				
Level	<input type="radio"/> Critical <input type="radio"/> Major <input checked="" type="radio"/> Minor <input type="radio"/> Notice				
Description					
This PCN is being issued to address that the appearance change of the accompanying cable for EV2U-RMR1 and EV2U-RMR2. A logo has been added to the molding.					

Affected Component Table		
Model	Current Part Number	New Part Number
EV2U-RMR2	EV2U-RMR2%	
EV2U-RMR1	EV2U-RMR1%	

Desc. Note
Innodisk anticipates no negative impact to customer’s application. There is no functional implication to customer's application but improve reliability, and qualification of these changes may not be necessary.

Summary of Change
The updated USB-A has added a trash logo to the molding, as shown from the left side cable to the right side cable in the picture. The function remains unchanged.  The new cable will be implemented for both standard and customized part numbers.  

Note
No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones. Innodisk apologizes for any inconvenience caused by this and appreciate your understanding. Innodisk promises that new items deliver quality and reliability for your application. If you have any further inquiry of our products or if you have any question about the specification of it, please contact Innodisk sales person. Thank you for your confidence in Innodisk in the past and looking forward to serving you in the near future.

Key Milestone Dates	
Effective Date	2024/Jun/21
*Recommend action: <input type="radio"/> Call back <input type="radio"/> All stock rework <input type="radio"/> Running change <input checked="" type="radio"/> Cut in Effective date	

Customer Impact of Change and Recommended Action
--

Please review the content and provide specific recommendation based on this document.

Innodisk anticipates no negative impact to customer’s application. There is no functional implication to customer's application but improve reliability, and qualification of these changes may not be necessary.

Revision History		
Date of Revision:	Revision Number:	Remark:
2024/Jun/21	E240011	


Director, JOHNNY WU  
Intelligent Peripheral Appliance Div.



Specialist, LEO CHEN  
Optical Product & RD Dept.



Senior Manager, CK HSU  
Optical Product & RD Dept.



**Headquarter(Taiwan) : Puppeteer** <https://www.innodisk.com> E-MAIL: [sales@innodisk.com](mailto:sales@innodisk.com)  
**TEL:** +886-2-7703-3000 **ADD:** 5F., No. 237, Sec. 1, Datong Rd., Xizhi Dist., New Taipei City 221, Taiwan  
**USA Office:** [usasales@innodisk.com](mailto:usasales@innodisk.com) / **Europe:** [eusales@innodisk.com](mailto:eusales@innodisk.com) / **Japan:** [jpsales@innodisk.com](mailto:jpsales@innodisk.com) / **China:** [sales\\_cn@innodisk.com](mailto:sales_cn@innodisk.com)