

PRODUCT END OF LIFE (EOL) NOTICE

1. EOL PRODUCTS

Product Name	Description
BW051 R.B	SBC 2.5" Board, INTEL Braswell series

2. EOL REASONS

INTEL LAN CHIP, i211AT (147-002110-200G) EOL, and the previous design didn't co-lay with i210. Meanwhile, CPU life cycle has nearly achieve the end, so PM suggests no re-layout and swap the demand to the recommended new model.

Supplier	Marketing Name
INTEL	IC CHIP,Giga LAN CTRL,WGI211AT SLJXZ/QFN-64(INTEL)RoHS

3. EOL MILESTONES

Milestone	Definition	Date
Last Order Date	This is the date for customers to place their last order. The product will no longer be available after this date.	2024/11/29
Last Shipment Date	This is the last delivery date of the product. 1. This date is negotiable with DFI's headquarter or its branch offices. 2. The delivery date will highly depend on its actual lead time.	2025/05/30
End of Service Date	This is the date DFI will: - Discontinue updating software - Discontinue adding features - Discontinue new OS support - Discontinue bug fixes RMA services will be available depending on DFI's RMA policy.	2025/11/28

4. Recommended Product Replacements:

Product Name	Description
EHL051	SBC 2.5" Board, INTEL Elkhart Lake series

Approved by:

Reviewed by:

Prepared by:

DFI Inc.

No.100, Huanhe St., Sijhih City, Taipei County 22154, Taiwan (R.O.C.)
Tel: +886-2-2694-2986 FAX: +886-2-2694-5815

Customer's Signature:

5. Products Affected/Order Codes:

Part Number	Model Name	Description
770-BW0512-000G	BW051-BB-N3160	BW051-BB-N3160: VGA, R.B F/G RoHS MOTHER BOARD
770-BW0512-100G	BW051-BB-E8000	BW051-BB-E8000: VGA, R.B F/G RoHS MOTHER BOARD
770-BW0512-200G	BW051-BB-N3060	BW051-BB-N3060: VGA, R.B F/G RoHS MOTHER BOARD
770-BW0512-300G	BW051-BB-N3160	BW051-BB-N3160:HDMI, R.B F/G RoHS MOTHER BOARD

6. Recommended Product Replacement Part Number:

Part Number	Model Name	Description
770-EHL0511-000G	EHL051-TCD-6425RE	EHL051-TCD-6425RE: R.A, Wide temp. (-40~85℃) F/G Mother Board RoHS
770-EHL0511-100G	EHL051-TCD-6416RE	EHL051-TCD-6416RE: R.A, Wide temp. (-40~85℃) F/G Mother Board RoHS
770-EHL0511-200G	EHL051-TCD-6214R	EHL051-TCD-6214RE: R.A, Wide temp. (-40~85℃) F/G Mother Board RoHS
770-EHL0511-300G	EHL051-TCD-6425E	EHL051-TCD-6425E: R.A, Wide temp. (-40~85℃) F/G Mother Board RoHS
770-EHL0511-400G	EHL051-TCD-6413E	EHL051-TCD-6413E: R.A, Wide temp. (-40~85℃) F/G Mother Board RoHS
770-EHL0511-500G	EHL051-TCD-6211E	EHL051-TCD-6211E: R.A, Wide temp. (-40~85℃) F/G Mother Board RoHS
770-EHL0511-600G	EHL051-BCD-J6412	EHL051-BCD-J6412: R.A, TPM 2.0, F/G Mother Board RoHS
770-EHL0511-700G	EHL051-BCD-N6210	EHL051-BCD-N6210: R.A, F/G Mother

DFI Inc.

No.100, Huanhe St., Sijhih City, Taipei County 22154, Taiwan (R.O.C.)
Tel: +886-2-2694-2986 FAX: +886-2-2694-5815

		Board RoHS
--	--	------------

DFI Inc.

No.100, Huanhe St., Sijhih City, Taipei County 22154, Taiwan (R.O.C.)
Tel: +886-2-2694-2986 FAX: +886-2-2694-5815