



Product Change Notification (PCN) Announcement

Title	DDR5 PMIC product change notice	Date	2025/Mar/28	Ref No.	D250228												
Models	DDR5 RDIMM-related Modules / CXL Memory Modules																
Level	<input type="radio"/> Critical <input type="radio"/> Major <input checked="" type="radio"/> Minor <input type="radio"/> Notice	Change Type	Others - PMIC														
Description																	
Key Characteristics of the Change:																	
Due to supply conditions, Innodisk hereby announces the product change plan for PMIC assembled in DDR5 RDIMM-related modules / CXL Memory Modules.																	
Innodisk module PN will stay the same.																	
Description:																	
<table><tr><th>Component</th><th colspan="2">EOL</th><th colspan="2">Replacement</th></tr><tr><td rowspan="2">PMIC</td><td>Montage</td><td>M88P5000A4</td><td rowspan="2">MPS</td><td rowspan="2">MPQ8895GU-0050-Z</td></tr><tr><td>Renesas</td><td>P8900-X0Z001FNG8</td></tr></table>						Component	EOL		Replacement		PMIC	Montage	M88P5000A4	MPS	MPQ8895GU-0050-Z	Renesas	P8900-X0Z001FNG8
Component	EOL		Replacement														
PMIC	Montage	M88P5000A4	MPS	MPQ8895GU-0050-Z													
	Renesas	P8900-X0Z001FNG8															

Affected Component Table	
Current Part Number	New Part Number
M5PZ-AGM2PC0Q-D%	(unchanged)
M5PZ-AGS2PC0Q-P%	(unchanged)
M5RV-AGM2AC0P-A%	(unchanged)
M5RV-AGM2CC0P-A%	(unchanged)
M5RV-AGS2A50P-B%	(unchanged)
M5RV-AGS2AC0P-B%	(unchanged)
M5RV-AGS2DC0P-B%	(unchanged)
M5RV-BGM2BC0P-A%	(unchanged)
M5RV-BGM2DC0P-A%	(unchanged)
M5RV-BGS2B50P-B%	(unchanged)
M5RV-BGS2BC0P-B%	(unchanged)
M5RV-BGS2DC0P-B%	(unchanged)
M5RZ-AGS2AC0Q-P%	(unchanged)
M5RZ-AGS2ACVP-P%	(unchanged)
M5RZ-BGS2BC0Q-P%	(unchanged)
M5RV-AGS2CC0P-B%	(unchanged)
M5RZ-AGH2AC0Q-A%	(unchanged)
M5RZ-AGM2AC0Q-D%	(unchanged)
M5RZ-AGM2ACVP-D%	(unchanged)
M5RZ-AGS2A50Q-P%	(unchanged)
M5RZ-AGS2A5VP-P%	(unchanged)
M5RZ-AGS2AC0Q-P%	(unchanged)
M5RZ-AGS2ACTO-P%	(unchanged)
M5RZ-AGS2ACVP-P%	(unchanged)
M5RZ-AGS2CC0Q-P%	(unchanged)
M5RZ-BGH2BC0Q-A%	(unchanged)
M5RZ-BGM2BC0Q-D%	(unchanged)
M5RZ-BGM2DC0Q-D%	(unchanged)
M5RZ-BGS2B50Q-P%	(unchanged)

Affected Component Table	
Current Part Number	New Part Number
M5RZ-BGS2B5VP-P%	(unchanged)
M5RZ-BGS2BC0Q-P%	(unchanged)
M5RZ-BGS2BCTO-P%	(unchanged)
M5RZ-BGS2BCVP-P%	(unchanged)
M5RZ-BGS2D50Q-P%	(unchanged)
M5RZ-BGS2D5VP-P%	(unchanged)
M5RZ-BGS2DC0Q-P%	(unchanged)
M5RZ-BGS2DCVP-P%	(unchanged)
M5RZ-FGHZAC0Q-M%	(unchanged)
M5RZ-GGHZBC0Q-M%	(unchanged)
MM111-5CGS1A1ACA00%	(unchanged)
M5R0-AGM2ACVP	(unchanged)
M5R0-AGS2A5VP	(unchanged)
M5R0-AGS2ACVP	(unchanged)
M5R0-BGM2BCVP	(unchanged)
M5R0-BGS2B5VP	(unchanged)
M5R0-BGS2BCVP	(unchanged)
M5R0-BGS2DCVP	(unchanged)
M5R0-AGS2ACZQ	(unchanged)
M5R0-AGS2ACVP	(unchanged)
M5R0-BGS2BCZQ	(unchanged)
M5R0-AGH2ACZQ	(unchanged)
M5R0-AGM2ACZQ	(unchanged)
M5R0-AGM2ACVP	(unchanged)
M5R0-AGS2A5VP	(unchanged)
M5R0-AGS2ACZQ	(unchanged)
M5R0-AGS2ACTO	(unchanged)
M5R0-AGS2ACVP	(unchanged)
M5R0-BGH2BCZQ	(unchanged)
M5R0-BGM2BCZQ	(unchanged)
M5R0-BGM2DCZQ	(unchanged)
M5R0-BGS2B5VP	(unchanged)
M5R0-BGS2BCZQ	(unchanged)
M5R0-BGS2BCTO	(unchanged)
M5R0-BGS2BCVP	(unchanged)
M5R0-BGS2D5VP	(unchanged)
M5R0-BGS2DCVP	(unchanged)
M5R0-FGHZACZQ	(unchanged)
M5R0-GGHZBCZQ	(unchanged)

Note
(1) For the availability of the replacement samples, please talk to the local salesperson and PM. (2) No response from customers will be deemed as acceptance of the change, which will be implemented according to the key milestones. Innodisk apologizes for any inconvenience this may cause and appreciates your understanding. (3) Innodisk promises that new items deliver quality and reliability, and are JEDEC compliant. If you have any further inquiries about our products or product specifications, please contact your Innodisk salesperson for support. (4) Innodisk reserves the right to process the product change if the PN is not listed. (5) The wild cards are represented here by percentage (%).

Key Milestone Dates	
Last Purchase Date	2025/Jun/30

Last Shipment Date	2025/Sep/30
<div>*Recommend action: <input type="radio"/> Call back <input type="radio"/> All stock rework <input type="radio"/> Running change <input checked="" type="radio"/> Cut in Effective date</div>	

Customer Impact of Change and Recommended Action

To minimize the impact of product supply, we suggest speeding up the transition. We will support you in making this transition smoothly to ensure a seamless process. Please contact Innodisk sales if you have any inquiries.

Director, SYLVIA CHENG
Embedded DRAM Div.

